

Airframe: 7550 Total Time Since New 8044 Landings

Engines: Pratt & Whitney PT6A-135

Left Engine: 1260 TSO Right Engine: 1260 TSO (0 SHOT)

SN: PCE92496 SN: PCE92570

(Engines Overhauled by Dallas Airmotive - 2/2006)

Propellers: Hartzell 4 blade props HCB4TN-3A

Left Prop: 430 TSO

Due OH: Jul 2026

SN: EA-1856

Right Prop: 430 TSO

Due OH Jul 2026

SN: EA-1854

**Avionics:** Bendix King & Garmin

Dual Bendix King KTR-908 Comms Bendix King Dual KNR-634 Navs

Bendix King KFC-300 AP & KCP-320 FD
Bendix King KDC-380 ADC
Sandel ST3400 3-ATI TAWS/RMI

Garmin GTX335R/GTX345R Transponders
Bendix King KRA-405 Radio Altimeter
Terrain Awareness & Warning System

Dual Bendix King KDR-806 ADF's Bendix King KAS-297A Altitude Alert/Preselect

Garmin GTN 625 GPS Primus 300 SL Color Radar

BF Goodrich Skywatch 497 Traffic Copilot HSI

## **OTHER EQUIPMENT:**

Exc. Boots ADS-B IN/OUT American Aviation Cowls & Stacks

Raisbeck Aft Body Strakes Cleveland Wheels and Brakes All logs since new

Known Ice Equipped Quick donning crew masks No known major damage history

134a Freon Air Cond. System Maintained by North Texas Aircraft 3926 lbs. useful load

## **INTERIOR:**

Executive/8 passengers, tan leather seats, tan carpet. Aft lav, cabinets, dividers, tables.

## **EXTERIOR:**

Matterhorn white w/blue & beige accent.

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.









Blackhawk Aerospace | 7601 Karl May Drive | Waco, TX 76708 | United States +1 (254) 755-6711 | aircraft@blackhawk.aero







